

# Active Travel Infrastucture - Ballyalbany Bridge

# Tree (or tree group) Survey Summary & Impacts - As a Quantum

#### Impact

To be removed to facilitate the development

To be retained with maintenance/mitigation required.

No impact

Count (Total)
5
0
19
24

Count (Total)

21%

0%

100%

Condition as per Tree Survey				
Good	Fair	Poor		
0	5	0		
0	0	0		
0	18	1		
0	23	1		

## Tree (or tree group) Survey Summary & Impacts - As a Percentage of Scheme Total

#### Impact

To be removed to facilitate the development

To be retained with maintenance/mitigation required.

No impact

79%

Condi	Condition as per Tree Survey			
Good	Fair	Poor		
0%	21%	0%		
0%	0%	0%		
0%	75%	4%		
0%	96%	4%		

Totals

Totals

## **Details of Trees/Tree Groups to be Removed**

ID	Species	Condition
T11	Western red cedar	Fair
T12	Western red cedar	Fair
T13	Western red cedar	Fair
T14	Sycamore	Fair
T15	Ash	Fair

